Original 31-Jan-17	FY 201	9 Throu	ah 1st Qtr	FY 2020 OI	hio River Sys	stem Lock	and Dam M	aior Mainte	nance Sche	dule	-			Heavy	Middle	Light	Contractor	Primary or	Auxiliary	No or	
														,		-5		Single Chamber	Chamber Closed	Intermittent	
		-																Closed	Oloseu	Olosules	
As of 14-Nov-18		3 Year																			
		Avg Tons																• •	•	•	
Project	Work Description Heavy Capacity Fleet	(M)	District	River	River Mile	Oct-18	Nov-18	Dec-18	Jan-19	Feb-19	Mar-19	Apr-19	May-19	Jun-19	Jul-19	Aug-19		Oct-19 FY-20	Nov-19	Dec-19	
Newburgh	Primary Chamber - Repair Miter Gates	75	Louisville	Ohio	776.0 R	•											FIFIS	F1-20			Primary Chamber Closed
Olmsted	ver Chamber - Replace Upper Miter Gate Anchor Arr	71	Louisville	Ohio	964.6 R	26															River Chamber Closed
		- / 1	Louisville	Offic	304.010	TBD															
Robert C. Byrd	Primary Chamber - Repair Miter Gates	42	Huntingtor	Ohio	279.2 L										8		30	1			Primary Chamber Closed
Markland	Auxiliary Chamber - Repair Filling Valve	52	Louisville	Ohio	531.5 L						•		-•				30				Auxiliary Chamber Closed
McAlpine	North Chamber - Prep for Replacement Miter Gate	68	Louisville	Ohio	606.8 L						4		9								North Chamber Intermittent Closures for Prep
Werapine		- 00	Louisville	Offic	000.0 E								13	6							of Miter Gate Replacement in 2020
Winfield Dam	Medium Capacity Fleet Dam - Repair Roller Gate #2	12	Huntington	Kanawha	31.1 R	•	. •														No Closures
	i i					1	8														
Pike Island	Auxiliary Chamber - Replace Sector Gear Pins	33	Pittsburgh	Ohio	84.3 L		13	21													Auxiliary Chamber Closed
Montgomery	Primary Chamber - Install Lower Bulkhead Slots	21	Pittsburgh	Ohio	31.7 R						•										chamber is crosed with restricted width lockage d. First half of job, the auxiliary chamber is opi
			_								11			14					except when t	the primary cha	mber is open. Second half of job, the primary cted width lockages every 2 hours for 20hrs/day
Willow Island	Primary Chamber - Repair Miter Gates	41	Huntingtor	Ohio	161.7 R									14							d width lockages for 4 hr/day. The auxiliary Primary Chamber Closed
Willow Island	Fillinary Chamber - Repair whiter Gates	41	riuntingtoi	Onio	101.7 K										8		30				
Winfield Dam	Repair Roller Gate #1	12	Huntington	Kanawha	31.1 R													1 17			No Closures
Maxwell Dam	Repair Dam Gates 3, 4, and 5	9	Pittsburgh	Monongahei	61.1 R														•		No Closures
Maxwell	Install Floating Mooring Bitts	9	Pittsburgh	Monongahel	61.1 R														4	13	Limited Closures to Install Floating Mooring E
Smithland	Light Capacity Fleet Replace Miter Gate and Culvert Valve Cylinders	68	Louisville	Ohio	918.5 R	•	•		•												One week Closure at One of two 1200' chamb
Ozzala III II. II. Old III.	Dams - Clean Intakes	Mania	No observed	O	- 1/ /	22	16		28		14										No Observes
Cordell Hull, Old Hickory, arkley, and Cheatham Dan		varies	Nashville	Cumbenano	various				28		14										No Closures
Pickwick Landing	mary Chamber - Install Replacement Culvert Valves	12	Nashville	Tennessee	206.7 L						21				25						Intermittent Closures - Twenty 10 hr closures during the period
Kentucky	Single Chamber - Machinery and Lock Wall Repairs	27	Nashville	Tennessee	22.3 R						21				23	•	•				Closure extended 15 days for TVA work on up
Smithland Dam	ingle Chamber - Repair and Recoating Upper Miter G	ate 68	Louisville	Ohio	918.5 R											6	15				No Closures
	·																1		19		
Smithland	Replace Miter Gate and Culvert Valve Cylinders	68	Louisville	Ohio	918.5 R													1	15		One 10 day closure period
	Nashville District																				
Chickamauga	Single Chamber - Modify Upper Landwall Miter Gate Anchorage Arm	1	Nashville	Tennessee	471.0 R						TBD (6 days	:)									Single Chamber Closed for 6 days, exact time
	Contractor																				
Allegheny River 2	Repair Lock Chamber Concrete, Landward Face	1	Pittsburgh	Allegheny	6.7 R			strictions in evation/weat		ber closure 5	5 Aug – 26 A	ug; 35' width	restriction 2	26 Aug – 9 S	Sept; chambe	er closure 9	Sept – 10 Oct;	35' width restr	ction 10 Oct -	25 Oct. Dates	
Emsworth	Geotechnical Borings Riverward of Auxiliary Chamber for Upper Ohio Project	16	Pittsburgh	Ohio	6.2 R	Very limited	l closures to	the auxiliary	y chamber la	ate winter thro	ough summe	er 2019 with	approximate	ly 30-day ad	dvance notice	e for NTNI n	otices. On-site	drilling to last	approximately	2 months at ea	ch location.
Dashields	Geotechnical Borings Riverward of Auxiliary Chamber for Upper Ohio Project	17	Pittsburgh	Ohio	13.3 L	Very limited	d closures to	the auxiliary	y chamber la	ate winter thro	ough summe	er 2019 with	approximate	ly 30-day ad	dvance notice	e for NTNI n	otices. On-site	drilling to last	approximately	2 months at ea	ch location.
Montgomery	Stabilize Middle Wall Crack	17	Pittsburgh	Ohio													ber up to 12 h	ours/day, Mon	thru Fri with 35	day advance	Industry Request - concurrent with Montgome
Dashields	Primary Chamber - Emergency Slope Stabilization behind Upper Guide Wall	20	Pittsburgh	Ohio			notice. No auxiliary chamber closures during FLEET work with Contractor utilizing FLEET closures to maximum extent possible. Unknown requirements for emergency stabilization known at this time. Will socialize plan once engineering investigation is complete and a scope of work is developed. Very unlikely for FY Industry Request - concurrent with Montgomery														
New Cumberland	nary Chamber - Upgrade to Hydraulic Operating Sys	29	Pittsburgh	Ohio	54.4 R	Short term chamber closures expected during the work to include up to five 48-hour closures and intermittent 8-hour closures between the hours of 0730 and 1600, Monday thru Friday. Industry Request - concurrent with Montgomery															
Racine Dam	Repair Tainter Gate #5	45	Huntington	Ohio	237.3 L	Developing plans and specs, do not know when work will be scheduled.															
Winfield	Repair Upper Land Wall Miter Gate Anchorage	12	Huntingtor	Kanawha	31.1 R	Work sched	duled for 29	May - 01 Jul	ly 2019.												Industry Request - concurrent with R.C. Byrd and Willow Island.
Greenup	Repair Emergency Gate Recess Concrete	38	Huntingtor	Ohio	341.1 L	Developing plans and specs, do not know when work will be scheduled,															
Greenup	Stabilize Middle Wall Crack	38	Huntingtor	Ohio	341.1 L	Work will cl	ose auxiliar	y chamber.	Work timefr	ame TBD, wi	ill advise wh	en known.									

